



Release Notes Bulletin

GEOSPATIAL
June 2021

TRIMBLE SX10 SCANNING TOTAL STATION INSTRUMENT FIRMWARE S2.4.35 RELEASE NOTES

Introduction

These release notes contain information about the Trimble® SX10 Scanning Total Station firmware version S2.4.35. These firmware versions are available for install and download using [Trimble Installation Manager](#).

Upgrading Firmware

If you have a Trimble SX10 Scanning Total Station running an older version of firmware, you can upgrade to version S2.4.35 yourself by following the steps of the [Firmware Update Procedure](#).


IMPORTANT NOTES:

- *It is not possible to install a firmware version that is prior to the firmware version your specific instrument shipped with.*
- *Once version S2.4.35 is installed, it is not possible to downgrade to a version lower than S2.2.52, if not in violation of the rule above.*

Checking current firmware version

You can check your Instrument's version of firmware using Trimble Access field software.

1. Turn on the Trimble SX10 Scanning Total.
2. Connect to the Trimble SX10 using a licensed Trimble Access controller/computer and launch General Survey.
 - a. Navigate to Instrument → Instrument settings.
 - i. Here you will see the Instrument name, serial number, firmware version and Wi-Fi channel.



www.trimble.com

© 2020, Trimble Inc. All rights reserved. Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.

Using the Trimble SX10 Scanning Total Station with other Trimble Products

Trimble SX10 Scanning Total Station firmware version S2.4.35 is compatible with the following Trimble survey field software.

- Trimble Access 2017.21 or later
- Trimble Access SDK
- Trimble Precision SDK

Note: For service interval warnings, Trimble Access 2017.20 or later is required

Note: For in-field camera calibration functionality, Trimble Access 2018.20 or later is required

Note: For Wi-Fi channel selection functionality, Trimble Access 2019.00 or later is required

IMPORTANT: *This version of Trimble SX10 Scanning Total Station firmware is not compatible with versions of Trimble survey field software older than those listed above. Please take note of the following information before upgrading your Trimble SX10 Scanning Total Station.*

Older controllers that you already own might need to be upgraded to their latest versions. Note that this will require a valid software warranty agreement for the Trimble survey field software. Please contact your local Trimble representative for more information regarding software warranties.

Please check the release notes for the respective Trimble survey office software for more specific product information.

Trimble always recommends that customers regularly check www.trimble.com and [Trimble Installation Manager](#) for the latest versions of software and firmware for all of their Trimble products.

New Features / Enhancements / Resolved Issues

The Trimble SX10 Scanning Total Station firmware version S2.4.35 includes the following new features and enhancements:

Version S2.4.35 – June 2021

- Resolution of an issue with poor video performance when paired with Trimble Access version 2019 or older. This issue was only in version S2.4.30
- Improvements to avoid "no communications" issues related to the IPCR 3 board and memory failures
- Added support for Tilt component serviceability
- Includes all updates from S2.4.30

Version S2.4.30 – March 2021 (Released, then withdrawn shortly after)

- Log Collector content improvements
- Service log content improvements
- Reliability improvement to the servo focus motor to prevent an issue where it could get stuck in one position
- Resolution of error related to switching from a cabled connection to WiFi connection where robotic connection would fail followed by error code 5004 instrument electronic level unavailable

Version S2.3.55 – October 2020

- Resolution of error codes 49.3.2.1.0 and 27.2.23.5.1 related to panorama capture
- Resolution of parasite points that could appear beyond 1km range at zenith
- Resolution of compensator issue where angles were not compensated after setting a 0° backsight

For more information

For more information contact your local Trimble Distribution Partner.