



Trimble X7

Firmware Version 2.3.22

Introduction

This document announces the release of firmware version 2.3.22 for the Trimble X7 3D laser scanner. The firmware update includes new enhancements, general updates and bug fixes.

Overview of update

- New indoor high productivity scan mode. Requires the new Trimble Perspective 2.1.3.1474.
- Improved image collection and save time
- Corrected issue with completion of image acquisition with upside down setup
- General improvements to laser pointer behavior
- Enhanced onboard diagnostics for instrument components
- Enhanced course tilt measurements
- Fixed intermittent issue with level status resetting to unknown after scan
- General improvements to thermal check
- General improvements to Wi-Fi communication
- Fixed SD Card file error after stopping scan
- Fixed diagnostics IMU heading measurement failure
- Corrected issue with Perspective reading projects created with Perspective Mobile app.

Legal notices

Trimble Inc.
Geospatial
10368 Westmoor Drive
Westminster, Colorado 800021
USA
800-361-1249 (toll free in USA)
+1-937-245-5154 Phone
+1-937-233-9441 Fax
www.trimble.com

Copyright and trademarks

© 2021, Trimble Inc. All rights reserved. Trimble, and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries.

Version: 2.3.22
Date: 21 Sept 2021